



SERVICE BULLETIN

Index Rev. 11

Aircraft Restoration Corporation

Revised Date: 15 May 2015

Subject:

Index of Service Bulletins applicable to Aircraft Restoration Corps STC modified airplanes.

Effectivity:

As described on specific STC Service Bulletin.

Service Bulletin Description:

1. 852-001, Rev. IR, Void
2. 852-002, Rev. IR, Void
3. 852-003, Rev. IR, Void
4. 852-004, Rev. IR, Boundary Layer STC SA00202SE Interference.
5. 852-005, Rev. A, Rib Interference Wing STA 49.00.
6. 852-006, Rev. IR, Outer Gear Door Interference with Side Brace.
7. 852-007, Rev. IR, Installation Procedures Clarification Emergency Gear Extension, PA-31T2, PA-42, PA-42-720.
8. 852-008, Rev. IR, Void
9. 852-009, Rev. IR, Void



Aircraft Restoration Corporation

SERVICE BULLETIN

Index Rev. 11

10. 852-010, Rev. A, MLG Retraction Actuator Spacer Installation.

11. 852-011, Rev. A, Installation of uplock roller spacer.