



# SERVICE BULLETIN

**NO. ARC-SB-852-007**

**Aircraft Restoration Corporation**

Date: 24 March 2011

Subject:

Installation Procedures Manual, Document IP-85280-01 part removal clarification.

Effectivity:

PA-31T2, PA-42, PA-42-720

Compliance:

Upon receipt.

Purpose:

To clarify wording in the Installation Procedures Manual, Document IP-85280-01 and to inspect the MLG Emergency Extension System.

Compliance:

At installation.

Approval:

ARC Engineering.

Material:

None

Instructions/Summary/Comments:

The Installation Procedures Manual, Document IP-85280-01 contains verbiage that can possibly be misconstrued by installation personal. On page 2, paragraph 2, item 3, it states: